


FIRE SAFETY ALERT: Steelcase LED Shelf Light



October 24, 2024

Environmental Health & Safety (EH&S) is asking University building coordinators, facility managers, units and departments to identify and unplug Steelcase LED Shelf Light fixtures (listed below) from building power sources due to the potential for fire and/or overheating. Steelcase LED Shelf Lights were involved in three separate incidents in two buildings on the Seattle campus between 2022 and 2024.

- **Steelcase LSL18** Standard Light
- **Steelcase LSL18YA** Daisy Chain Starter Light
- **Steelcase LSL18YB** Daisy Chain Secondary Light
- Associated daisy-chain cords
- Associated power cords



IMMEDIATE ACTIONS

Check for Steelcase LED Shelf Lights LSL18, LSL18YA, LSL18YB in your building.

If you find them, please do the following:

1. **Turn off** the shelf lights.
2. **Disconnect the power cord** from the electrical wall outlet. Please be sure to keep cords with the associated light fixture.
3. **Document the location** of any of these lights in your building and note if any heat damage is observed.
4. Coordinate with your facility manager/building coordinator to **report this information to EH&S in the [spreadsheet](#)**.

QUESTIONS

Scott Nelson, PE
Building and Fire Safety Manager
uwfire@uw.edu
206-221-7055

Your [building coordinator](#) or
facility manager

WHAT WE KNOW

There is evidence to suggest problems within the light fixture and/or the installation (e.g., daisy-chaining). If the units are not properly installed, an overheating event can occur.

When daisy-chaining Steelcase Light Shelf Units, the [specification guide](#) (starting on page 102) indicates the first light unit in the series must be a model LSL18YA unit followed by up to two LSL18YB units. The model LSL18 is a standalone unit and must not be daisy-chained with other light units.

WHAT'S NEXT

Environmental Health & Safety will follow up with units that [reported](#) Steelcase LED Shelf Lights to EH&S. Suspect light fixtures and associated cords will be collected by EH&S so they cannot be reused.

EH&S and UW Facilities are continuing to investigate and following up on the potential causes of the fires/overheating events with the involvement of the manufacturer and vendor. The Seattle Fire Department has been notified of the incidents.

More information will be shared as it becomes available.



REFERENCES

Steelcase LED Shelf Light:

www.steelcase.com/products/lighting/led-shelf-light/

Specification Guide (LED shelf light information starts on page 102):

www.steelcase.com/content/uploads/2024/10/worktools-spec-guide.pdf